

Cadastral Map 48 – Structural Damage (Nürnberg, Vestnertorgraben, Rathenauplatz, Wöhrder Wiese, Lorenzkirche)

working_title: Cadastral Map 48 – Structural Damage

signature: StadtAN A 4/VI Nr. 2222/1

external_url: https://online-service2.nuernberg.de/stadtarchiv/objekt_start.fau?prj=verzeichnungen&dm=Archivalien&ref=145786

urltitle: Stadtarchiv Nürnberg, inventory database

orientation: North on top

papersize: 50 x 50 cm

scale: 1:2000

place: *name:* Nürnberg

internal_id: 77

district: Vestnertorgraben, Rathenauplatz, Wöhrder Wiese, Lorenzkirche

repository: *name:* Stadtarchiv Nürnberg

internal_id: 14

data: *FDM:* KsN

copyright_holder: Nürnberg Stadtarchiv

creator: [Stadt Nürnberg] |Quelle: Onlinedatenbank, Stadtarchiv Nürnberg|

creator_en: [City of Nuremberg] |Source: Online repository, City Archive Nuremberg|

language: German

paper_type: paper

printing_technique: hand colouring

description: 'Photoalgraphie' with hand-drawn indications of damage. [Mapped area: Vestnertorgraben in the northwest, today's Rathenauplatz in the northeast, the Wöhrder Wiese in the southeast, and St. Lorenz Church in the southwest.]
|Source: City Archive Nuremberg|

basemap: *title:* Base Map Cadastral Map 48

description: Base map showing Vestnertorgraben in the northwest, today's Rathenauplatz in the northeast, the Wöhrder Wiese in the southeast, and St. Lorenz Church in the southwest.

date: 1940-09

internal_id: 244

layers: - *date:* 1945

estimated: true

description: "Für die Öffentlichkeit gesperrt"

War damage marked in red in the north-eastern part of the historical city centre, north of the river Pegnitz, both inside and outside the historical city walls.

images: - *filename:* StadtAN_A4_VI_2222_1.TIF

title: A4 VI 2222/1

internal_id: 133